

RECALL 21V724. 2021-578 REMEDY INSTRUCTIONS



Make(s): Alta Travel Trailer
Model(s): Many, See Below
Model Year(s): 2022

Concern:
The LP Gas quick disconnect fitting installed onto the exterior grill by Forest River is not tight, allowing for LP Gas to leak.

Repair Code: RC-026-12-00-004095
Allotted Time: .60 HRS.
Inspection Code: RC-026-05-00-004094
Allotted Time: .10 HRS.
Photo(s) Required: YES
Prior Authorization Required: NO
Part(s) Kit Number: N/A
Part(s) Return: NO

Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

MODELS: ALT2100MBH, ALT2800KBH, ALT2810KIK & ALT3150KBH

STEP 1: LOCATE THE LP GAS QUICK DISCONNECT THAT IS INSTALLED TO THE EXTERIOR GRILL;

STEP 2: DETERMINE IF THE LP GAS QUICK DISCONNECT IS LOOSE;

- CONNECT THE PROVIDED LP GAS HOSE TO THE QUICK DISCONNECT UNDER THE TRAILER
- CONNECT THE OTHER END OF THE PROVIDED LP GAS HOSE TO THE EXTERIOR GRILL
- TURN ON THE LP GAS SUPPLY AND OPEN THE BOTH QUICK DISCONNECT VALVES
- SPRAY WITH SOAPY WATER OR ANOTHER LP GAS LEAK DETECTOR FLUID
- VERIFY THE LP QUICK DISCONNECT ON THE EXTERIOR GRILL IS POINTED VERTICALLY DOWN



STEP 3: IF THERE IS LEAKING LP GAS, REPAIR THE FITTING;

- TIGHTEN THE QUICK DISCONNECT THAT IS ATTACHED TO THE EXTERIOR GRILL
- VERIFY THE LP QUICK DISCONNECT ON THE EXTERIOR GRILL IS POINTED VERTICALLY DOWN
- SPRAY WITH SOAPY WATER OR ANOTHER LP GAS LEAK DETECTOR FLUID UNTIL THERE ARE NO BUBBLES PRESENT THAT INDICATE A LEAK

STEP 4: IGNITE THE EXTERIOR GRILL AND BURN OFF THE APPLIANCE;

STEP 5: CLAIM THE APPROPRIATE CODES LISTED AT THE TOP.