

*** IMPORTANT SAFETY RECALL*** NHTSA Recall No. 21E-033 Cummins Campaign #C2451 Final Notice



Cummins PowerDrive™ systems for NHTSA Recall 21E-033:

PowerDrive Serial Number		Vehicle Identification Number (VIN)
83500137		1BABNBUA7LF37
83500169	UNASSIGNED	1BABNBUAXLF37



*** IMPORTANT SAFETY RECALL*** NHTSA Recall No. 21E-033 Cummins Campaign #C2451

Month Day, Year

Dear Cummins Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in certain Cummins PowerDrive™ electric drivetrain systems that were manufactured between June 1, 2018 and February 23, 2021.

This notice applies to the PowerDrive electric drivetrain systems in your vehicle listed on the enclosed table.

You previously received a letter informing you of this recall and informing you that Cummins was developing a remedy. A remedy is now available for your vehicle.

WHAT IS THE PROBLEM?

The subject electric drivetrain systems may experience a condition that results in the loss of electrically assisted power steering. Power steering functionality is restored after a key switch recycle.

In the event of loss of power steering assist, manual steering functionality is retained but would require increased steering effort, particularly at lower speeds, increasing the risk of a crash.

WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins has released field Safety Campaign #C2451 "BES CM0904 EV104B Communication Harness Safety Campaign" to correct this condition by updating the wire harnesses for accessory inverters and providing improved electrical shielding. This campaign is currently available at Cummins Distributors and authorized Warranty Dealers. The repair will be completed free of charge and most applications will require approximately 1 hour to complete.

WHAT SHOULD YOU DO?

Contact the nearest Cummins Distributor or authorized Warranty Dealer to arrange to have this campaign performed on your drivetrain system. The distributor or dealer will work with you to schedule the best date to complete this repair.

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800- CUMMINS (1-800-286-6467), or visit our website at care.cummins.com.



If you have a complaint relative to this recall, you may report it to the following:

Administrator National Highway Traffic Safety Administration 1200 New Jersey Avenue, SE Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

If you have not registered your Cummins product, please complete the enclosed registration card or register your product at https://prodreg.cummins.com/prodreg/#/webform/contactInfo.

If you are no longer the owner of the vehicle listed on the enclosed table, please forward this notice to the new owner or provide the new owner's contact information to Cummins so that we can notify them of this recall.

Federal law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. Also, it is a violation of Federal law for a dealer to deliver a new vehicle or equipment covered by this recall notice under a sale or lease until the defect has been remedied.

Cummins is taking this action in the interest of safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,

Campaign Administrator Cummins Inc.