



September, 2024

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2018 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 21S10 - Continental Tire Inspection
and Description:

What is the issue? Continental Tires the Americas (CTA) has initiated a safety recall for tires that may have an overcure condition. On your vehicle, it is possible that an original factory installed Continental/General tire could have this condition.

According to CTA, an overcured tire may experience a carcass break in the sidewall with sudden air loss or could develop a belt edge separation that could lead to a partial or full tread/belt loss. These conditions may increase the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Septiembre de, 2024

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2018 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 21S10 - Inspección de llantas Continental

¿Cuál es el problema? Continental Tires the Americas (CTA) ha iniciado una campaña de seguridad para las llantas que pudiesen tener una condición de sobrecurado. Es posible que una llanta Continental/General instalada de fábrica original en su vehículo presente esta condición.

Según CTA, una llanta sobrecurada podría experimentar una rotura de la carcasa en el flanco con una repentina pérdida de aire o bien podría desarrollar una separación del borde de la banda que podría ocasionar una pérdida parcial o total de la banda de rodadura/banda. Estas condiciones podrían aumentar el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atenciic en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0730217 A / 00000000000011 / 11



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

