



Your vehicle has a safety recall!

LICENSE PLATE
MAKE/MODEL
VIN

RECALL / RETIRO

Non-deployment of Side and Curtain Shield Airbags May Occur (21TA01)

DESCRIPTION / DESCRIPCIÓN

An airbag system wire in the driver-side front door can be damaged, resulting in non-deployment of the Side and Curtain Shield airbags, increasing the risk of injury in a crash.

RISK / RIESGO

This may prevent the side airbag and curtain shield airbag on the driver side from deploying in certain types of collisions, increasing the risk of injury in the event of a crash where those airbags are needed.

FIX / SOLUCIÓN



Scan this QR code to find a local authorized dealer that will inspect the driver-side front door wire harness and, if necessary, replace it with an improved one FREE OF CHARGE OR CALL 800-331-4331.

This program is sponsored by Toyota Motor North America and is powered by Carma Project.



U.S. Department of Transportation



Safety is our mission. Learn how this notice got to your car at carmaprotects.com.

Hablamos Español



Su vehículo se ve afectado por una
CAMPAÑA DE SEGURIDAD
URGENTE!