



TOYOTA

SCHEDULE YOUR APPOINTMENT

1-888-270-9371

[REDACTED] : REMINDER, SAFETY RECALL NOTICE FOR 2009 TOYOTA VENZA

SIDE-IMPACT COLLISIONS ACCOUNT FOR 22% OF CAR-RELATED DEATHS.*

**Source: Insurance Institute for Highway Safety (IIHS) 2021*

SCHEDULE YOUR APPOINTMENT

The safety issue

A safety defect exists in certain 2009-2015 model year Venza vehicles that could prevent the driver’s side and curtain shield airbags from deploying in certain types of collisions, increasing the risk of injury. (NHTSA ID 21V-257)

Why you’re getting this

Our records indicate that you are the current owner of this Toyota Venza vehicle. VIN **[REDACTED]**

What you need to do

Contact an authorized Toyota dealer to schedule an appointment. You’ll need your VIN - it’s included above.

What to expect

During your appointment, we will inspect the driver-side front door wire harness, and, if necessary, replace it with an improved one **FREE OF CHARGE**. The process will take approximately **1.5 hours**.

SCHEDULE YOUR APPOINTMENT



Call 1-888-270-9371, scan the QR code, or go to toyota.com/dealers to find your preferred dealer.



PROGRAME SU CITA
1-888-270-9371

**[REDACTED] : RECORDATORIO, AVISO DE RETIRO DE SEGURIDAD
PARA EL TOYOTA VENZA 2009**

LAS COLISIONES DE IMPACTO LATERAL REPRESENTAN EL 22% DE LAS MUERTES RELACIONADAS CON AUTOMÓVILES.*

**Fuente: Insurance Institute for Highway Safety (IIHS) 2021*

PROGRAME SU CITA

El problema de seguridad

Existe un defecto de seguridad en ciertos vehículos Venza de año 2009-2015 que podría evitar que las bolsas de aire lateral y de cortina del lado del conductor se desplieguen en ciertos tipos de colisiones, lo que aumenta el riesgo de lesiones. (NHTSA ID 21V-257)

¿Por qué está recibiendo esto?

Nuestros registros indican que usted es el propietario actual de este vehículo Toyota Venza. VIN **[REDACTED]**

¿Qué necesita hacer?

Comuníquese con cualquier concesionario Toyota autorizado para hacer una cita. Necesitará su VIN, está incluido arriba.

¿Qué esperar?

Durante su cita, inspeccionaremos el arnés de cables de la puerta delantera del lado del conductor y, si es necesario, lo reemplazaremos por uno mejorado **SIN CARGO**. El proceso tomará aproximadamente **1.5 horas**.

PROGRAME SU CITA



Llame al 1-888-270-9371, escanee el código QR o vaya a toyota.com/dealers para encontrar su concesionario preferido.



[unsubscribe](#)