

[View in Browser](#)



SCHEDULE YOUR APPOINTMENT
1-888-270-9371

**REMINDER, SAFETY
RECALL NOTICE
FOR 2011 TOYOTA VENZA**



SCHEDULE YOUR APPOINTMENT

OUR RECORDS INDICATE YOUR VEHICLE IS PART OF A SAFETY RECALL.

VEHICLE:	Certain 2009-2015 model year Venza
VIN:	[REDACTED]
RECALL:	NHTSA ID: 21V-257, Non-deployment of side and curtain shield airbags may occur
SAFETY:	You may be at increased risk of injury in the event of a crash
COST:	FREE OF CHARGE

The issue

A safety defect exists in certain 2009-2015 model year Venza vehicles that could prevent the driver’s side and curtain shield airbags from deploying in certain types of collisions, increasing the risk of injury. (NHTSA ID 21V-257)

How to make sure your loved ones are protected

Contact an authorized Toyota dealer to schedule an appointment to inspect the driver-side front door wire harness, and, if necessary, replace it with an improved one **FREE OF CHARGE**. The process will take approximately **1.5 hours**.

SCHEDULE YOUR APPOINTMENT

Call and schedule an appointment now. Scan the QR code, or go to toyota.com/dealers to find your preferred dealer.



PROGRAME SU CITA
1-888-270-9371

RECORDATORIO, AVISO DE RETIRO DE SEGURIDAD PARA EL TOYOTA VENZA 2011



PROGRAME SU CITA

NUESTROS REGISTROS INDICAN QUE SU VEHÍCULO ES PARTE DE UN AVISO DE RETIRO DE SEGURIDAD.

VEHÍCULO:	Certain 2009-2015 model year Venza
VIN:	[REDACTED]
RETIRO:	ID DE NHTSA: 21V-257, Puede ocurrir que las bolsas de aire laterales y de cortina no se desplieguen
SEGURIDAD:	Puede tener un mayor riesgo de lesiones en caso de un choque
COSTO:	SIN CARGO

El problema

Existe un defecto de seguridad en ciertos vehículos Venza de año 2009-2015 que podría evitar que las bolsas de aire lateral y de cortina del lado del conductor se desplieguen en ciertos tipos de colisiones, lo que aumenta el riesgo de lesiones. (NHTSA ID 21V-257)

Cómo asegurarse de que sus seres queridos estén protegidos

Comuníquese con cualquier concesionario Toyota autorizado para programar una cita para inspeccionar el arnés de cables de la puerta delantera del lado del conductor y si es necesario, reemplazarlo con uno mejorado **SIN CARGO**. El proceso tomará aproximadamente **1.5 hours**.

PROGRAME SU CITA

Llame y programe una cita ahora. Escanee el código QR o vaya a toyota.com/dealers para encontrar su concesionario preferido.



[unsubscribe](#)