



L I N C O L N

Lincoln  
P.O. Box 1904  
Dearborn, Michigan 48121-1904



0001895 01 / 000000003 / 3



February 2024



**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2021 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**KEY INFORMATION**

- Your vehicle is involved in an important safety recall
- Your safety is important to us. Schedule an appointment to have service procedure completed
- This procedure will be performed free of charge

**Recall Number 21S34 - Battery Cable Contact BISG/AC and Description:**

**What is the Issue?**

On your vehicle, the battery cable wire harness may not be properly secured, allowing contact with the A/C compressor pulley.

Over time, the A/C pulley may rub through the wire harness insulation and contact the unfused positive battery (B+) circuit, which may result in a short circuit and potential fire.

**What Are We Asking You To Do?**

Please contact your dealer to schedule an appointment to have this important service procedure completed. If you do not already have a servicing dealer, you can access [lincoln.com/support](https://lincoln.com/support) for dealer addresses, maps and driving instructions.

The vehicle owner is responsible for having this service action performed. Lincoln reserves the right to deny coverage for any vehicle damage that may result from failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

**Service Assistance:**

If you have additional questions, please contact the Lincoln Customer Relationship Center at 1-866-436-7332 and one of our representatives will be happy to assist you. For the hearing impaired call 1-800-232-5952 (TDD). Office Hours are Monday through Friday: 8:00AM - 5:00PM (Your Local Time).

If you wish to contact us through the Internet, our address is: [lincoln.com/support](https://lincoln.com/support).

If your authorized dealer has recently completed this recall repair, please disregard this reminder.

We apologize for any inconvenience this may cause and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

Thank you for your attention to this important matter.

Lincoln



L I N C O L N

Lincoln  
P. O. Box 1904  
Dearborn, Michigan 48121



0001895 01 / 000000003 / 3



Febrero de 2024



**\*\*\* RECORDATORIO DE CAMPAÑA DE SEGURIDAD IMPORTANTE \*\*\***

Según nuestros registros, en su 2021 Aviator no se han realizado las reparaciones necesarias correspondientes a esta campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**INFORMACIÓN CLAVE**

- Su vehículo ha sido incluido en una importante campaña de seguridad.
- Su seguridad es muy importante para nosotros. Programe una cita para completar el procedimiento de servicio.
- Este procedimiento se llevará a cabo sin costo alguno.
- *Si necesita ayuda o tiene alguna pregunta, por favor llame al Centro de Relación con Clientes al 1-866-436-7332 y presione 2 para Español.*

**Número y descripción de la campaña:**

**21S34 - BISG/CA del contacto del cable de la batería**

**¿Cuál es el problema?**

En su vehículo, el arnés de la batería podría no estar correctamente asegurado, lo cual hace posible el contacto con la polea del compresor del A/C.

Con el paso del tiempo, la polea del A/C podría rozar en el aislamiento del arnés y generar contacto con el circuito positivo de la batería (B+) sin fusible, lo cual podría generar un cortocircuito y un posible incendio.

**¿Qué le solicitamos hacer?**

Comuníquese con su distribuidor a fin de programar una cita para llevar a cabo este importante procedimiento de servicio. Si aún no tiene un distribuidor para realizar el servicio, puede acceder a [lincoln.com/support](http://lincoln.com/support) para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.

El propietario del vehículo es responsable de realizar estas acciones de servicio. Lincoln se reserva el derecho de negar la cobertura en caso de que el vehículo hubiese sufrido daños por no haber realizado la campaña de manera oportuna. Por lo tanto, le solicitamos que realice esta campaña lo antes posible.

**Servicio de asistencia:**

Si tiene preguntas, comuníquese con el Centro de Relación con Clientes de Lincoln al 1-866-436-7332 y uno de nuestros representantes con gusto lo atenderá. Las personas con problemas de audición pueden llamar al 1-800-232-5952 (TDD). El horario de atención es de lunes a viernes, de 8:00 a.m. a 5:00 p.m. (hora local).

Si desea comunicarse con nosotros a través de Internet, nuestra dirección es: [lincoln.com/support](https://lincoln.com/support).

Si ya realizó esta reparación en su distribuidor autorizado, ignore este aviso.

Lamentamos cualquier inconveniente causado y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

Gracias por su atención en este asunto sumamente importante.

Lincoln