

IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN:

NHTSA Recall # 21V-545

Tiffin Recall # TIF-117

Cummins Recall # C2465

August 27, 2025

Cummins L9 engine, fuel hose leaks

This is a reminder that your motorhome has an open safety recall. If this recall does not apply or has already been completed, please email recalls@tiffinmotorhomes.com.

VIN:

ESN:

ISD:

Dear Tiffin Motorhome Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Tiffin Motorhomes has decided that a defect, which relates to motor vehicle safety, exists on the following models of motorhomes: **2021 and 2022 Allegro Bus motorhomes and 2021 and 2022 Phaeton motorhomes that were built between October 2020 and July 2021.**

Tiffin Motorhomes was notified by Cummins, Inc of a defect that exists on specific L9 engines manufactured by Cummins between March 27, 2019, and June 15, 2021. These specific engines are installed on chassis used by Tiffin Motorhomes to build the Allegro Bus and Phaeton models of motorhomes.

Cummins has determined that a fuel leak may occur in the fuel hoses between the fuel pump and remote filter head. A fuel leak in the presence of an ignition source may increase the risk of a fire. Persons operating in or around the vehicle may see smoke before sufficient heat creates a fire.

Cummins has released field Safety Campaign #C2465 L9 CM2350 L133C and L9 CM2450 L126B Remote Mount Stage 2 Fuel Hose Safety Campaign to correct this condition by replacing the subject fuel lines with fuel lines of a new design. This campaign is currently available at Cummins Distributors and authorized Warranty Dealers. The repair will be completed free of charge, and most applications will require approximately 2 hours to complete.

Contact the nearest Cummins Distributor or authorized Warranty Dealer to arrange to have this campaign performed on your engine. The distributor or dealer will work with you to schedule the best date to complete this repair. Cummins will need both the ESN and ISD for your motorhome, that information is located at the top of this notification.

We urge you to have this repair performed as soon as possible. In the meantime, however, Cummins advises you to periodically check the remote fuel filter hoses for signs of leaking and immediately seek repairs if leaks are identified.

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800- CUMMINS (1-800-286-6467) or visit their website at care.cummins.com.

If you do not own the vehicle that corresponds to the identification number which appears on this Recall Notification, please return the notification to the Tiffin Warranty Department with any information you can furnish that will assist us in locating the present owner. You may also call us at 256-356-8661 ext. 2176 or email jeannie.madden@tiffinmotorhomes.com.

If, after contacting Cummins, you have further questions, please contact the Tiffin Recall Department, at 1-256-356-8661, 8:00 a.m. to 3:30 p.m., Central Time. You may also wish to notify the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC 20590, or phone 1-888-327-4236 (TTY: 1-800-424-9153): or go to <http://www.safercar.gov>.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

Tiffin Recall Department