

Trouble viewing this email? [Open it in your browser >](#)



IMPORTANT SAFETY RECALL UPDATE

■■■■,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Our records indicate that you are the owner of a **Polaris Slingshot** with VIN 57■■■■■■■■■■ affected by Safety Recall T 21 01

Slingshot vehicles may have rear wheel studs that were not pressed into the axle fully during the supplier's assembly process. An improperly installed rear wheel stud could lead to loosening of the rear lug nuts, resulting in a loose or detached rear wheel during operation, increasing the risk of a crash. Prior to a crash, wheel noise or vibration could occur

Owner Next Steps:

- Visit our [Product Safety Recall](#) web page to verify if your Slingshot is impacted by this safety recall. Search for the model or vehicle identification number (VIN) on the site to confirm.
- Schedule an appointment with an authorized Slingshot dealer. Do not attempt repairs yourself. Repairs must be done by an authorized Slingshot dealer. Your local dealer can be found on our [Dealer Locator](#) web page.
- Your Slingshot dealer is in the best position to answer your questions, but you may also contact our Polaris Owner Connection Department at **1 855 863 2284** to speak with a representative.

Dealership Next Steps:

- Authorized dealers will inspect, and if needed, replace the rear axle on affected vehicle at no cost to you. This repair should take approximately 2 hours. They have been instructed to repair your vehicle.

We apologize for this inconvenience and assure you that we are committed to customer satisfaction for riders to enjoy

-Polaris Slingshot

Received This Notice In Error?

This notice was sent according to our most current registration information. If you no longer own this vehicle, contact your dealer to complete a transfer of ownership. Federal law requires that any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within 10 working days after the day on which the notice is received.

This email was sent by Polaris Slingshot to jaxxpr@yahoo.com because you are a registered owner of a Slingshot affected by a recent safety recall notice. Please do not reply to this email. To contact us, please call us at 1-800-POLARIS or visit our [help page](#).

© 2022 Polaris Industries Inc.
2100 Highway 55, Medina, MN 55340, USA