



March, 2022

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2020 Corsair has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** **21S44 - Rear/360 Camera IPMB Blue Screen**

**What is the issue?** On your vehicle, the 360-degree camera display, which includes the rear-view camera, may intermittently display a blue image on the media touchscreen upon shifting into reverse.

The loss of rearview camera image during a backing event can reduce the driver's view of what is behind the vehicle, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [lincoln.com/support](http://lincoln.com/support).

Thank you for your attention to this very important matter.

Marzo de, 2022

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2020 Corsair las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** **21S44 - Pantalla azul de IPMB de Cámara Trasera/360**

**¿Cuál es el problema?** En su vehículo, la pantalla de la cámara de 360 grados, que incluye la cámara trasera, podría mostrar de forma intermitente una imagen en azul en la pantalla táctil de medios luego de cambiar a reversa.

La pérdida de imagen de la cámara trasera durante un evento de retroceso puede reducir la vista del conductor de lo que hay detrás del vehículo, lo cual aumenta el riesgo de sufrir un choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [lincoln.com/support](http://lincoln.com/support).

Gracias por su atenciic en este asunto sumamente importante.




THE LINCOLN MOTOR COMPANY

P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0081252 A / 000000000000085 / 85



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

