



Ford Motor Company
Ford Customer Service Division
P.O. Box 1904
Dearborn, Michigan 48121 1904



0003674 01 / 000000003 / 2



June 2023



*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2020 Ranger has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

KEY INFORMATION

- Your vehicle is involved in an important safety recall
- Your safety is important to us. Schedule an appointment to have service procedure completed
- This procedure will be performed free of charge

Recall Number 21C24 - Child Restraint RAP Cab rear ISOFIX and Description:

What is the Issue? On your vehicle, the rear seat head restraints may interfere with proper installation of certain taller child seats. Additionally, the lower rear child seat anchorages on your vehicle may be improperly aligned which may increase the difficulty to install a child seat with rigid anchor attachments.

If a child seat is not properly installed, it can increase the risk of injury in a crash.

What Are We Asking You To Do? Please contact your dealer to schedule an appointment to have this important service procedure completed. If you do not already have a servicing dealer, you can access ford.com/support for dealer addresses, maps and driving instructions.

The vehicle owner is responsible for having this service action performed. Ford Motor Company reserves the right to deny coverage for any vehicle damage that may result from failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

Service Assistance: If you have additional questions, please contact the Ford Motor Company Customer Relationship Center at 1-866-436-7332 and one of our representatives will be happy to assist you. For the hearing impaired call 1-800-232-5952 (TDD). Office Hours are Monday through Friday: 8:00AM - 5:00PM (Your Local Time).

If you wish to contact us through the Internet, our address is: ford.com/support.

If your authorized dealer has recently completed this recall repair, please disregard this reminder.

We apologize for any inconvenience this may cause and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

Thank you for your attention to this important matter.

Ford Customer Service Division



Ford Motor Company
 División de Servicio al Cliente de Ford
 P. O. Box 1904
 Dearborn, Michigan 48121



0003674 01 / 000000003 / 2



Junio de 2023



*** * * RECORDATORIO DE CAMPAÑA DE SEGURIDAD IMPORTANTE * * ***

Según nuestros registros, en su 2020 Ranger no se han realizado las reparaciones necesarias correspondientes a esta campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

INFORMACIÓN CLAVE

- Su vehículo ha sido incluido en una importante campaña de seguridad.
- Su seguridad es muy importante para nosotros. Programe una cita para completar el procedimiento de servicio.
- Este procedimiento se llevará a cabo sin costo alguno.
- *Si necesita ayuda o tiene alguna pregunta, por favor llame al Centro de Relación con Clientes al 1-866-436-7332 y presione 2 para Español.*

Número y descripción de la campaña:

21C24 - ISOFIX trasero de asiento de seguridad para niños RAP Cab

¿Cuál es el problema?

Las cabeceras del asiento trasero de su vehículo podrían interferir con la correcta instalación de algunos asientos para niños más altos. Adicionalmente, los anclajes inferiores traseros del asiento para niños de su vehículo podrían estar incorrectamente alineados, lo cual podría aumentar la dificultad para instalar un asiento para niños con conexión de anclaje rígido.

Si un asiento para niños no está correctamente instalado, el riesgo de sufrir lesiones en caso de choque aumenta.

¿Qué le solicitamos hacer?

Comuníquese con su distribuidor a fin de programar una cita para llevar a cabo este importante procedimiento de servicio. Si aún no tiene un distribuidor para realizar el servicio, puede acceder a ford.com/support para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.

El propietario del vehículo es responsable de realizar estas acciones de servicio. Ford Motor Company se reserva el derecho de negar la cobertura en caso de que el vehículo hubiese sufrido daños por no haber realizado la campaña de manera oportuna. Por lo tanto, le solicitamos que realice esta campaña lo antes posible.

Servicio de asistencia:

Si tiene preguntas, comuníquese con el Centro de Relación con Clientes de Ford Motor Company al 1-866-436-7332 y uno de nuestros representantes con gusto lo atenderá. Las personas con problemas de audición pueden llamar al 1-800-232-5952 (TDD). El horario de atención es de lunes a viernes, de 8:00 a.m. a 5:00 p.m. (hora local).

Si desea comunicarse con nosotros a través de Internet, nuestra dirección es: [**ford.com/support**](https://ford.com/support).

Si ya realizó esta reparación en su distribuidor autorizado, ignore este aviso.

Lamentamos cualquier inconveniente causado y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

Gracias por su atención en este asunto sumamente importante.

Ford, División de Servicio al Cliente