



February, 2025

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2021 Bronco Sport has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 21C31 - FMVSS 135 Test Results for 2021 1.5L Bronco Sport & Escape with Vacuum
and Description: Boost

What is the issue? If your vehicle's brake vacuum booster fails, your vehicle may exceed stopping distance requirements specified by Federal Motor Vehicle Safety Standard No. 135 Light Vehicle Brake Systems.

You may experience increased brake pedal forces and extended stopping distance, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2025

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en su 2021 Bronco Sport las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 21C31 - FMVSS 135 Resultados de pruebas para 1.5L Bronco Sport y Escape 2021 con reforzador de vacío

¿Cuál es el problema? Si el reforzador de vacío del freno de su vehículo falla, el vehículo podría exceder los requisitos de distancia de detención especificados por la norma federal de seguridad de vehículos de motor n.º 135 Sistemas de frenos de vehículos livianos.

Es posible que experimente mayores fuerzas en el pedal del freno y una distancia de detención extendida, lo cual aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0001702 A / 000000000000096 / 96



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

