



March, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 F-250 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **21S49 - AFS Airbag PV Failure on Lariat, Platinum, and Limited Series**
and Description:

What is the issue? On your vehicle, the strength of the driver's side airbag cover may be insufficient after high mileage / extended time in the field.

In the event of a crash necessitating deployment of the frontal airbags, a driver airbag could project a fragment or fragments of the airbag cover toward the occupants, increasing the risk of injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Marzo de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2022 F-250 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **21S49 - Falla de PV de la bolsa de aire de AFS en Lariat, Platinum y Limited**

¿Cuál es el problema? La solidez de la cubierta de la bolsa de aire del lado del conductor de su vehículo podría ser insuficiente después de recorrer muchos kilómetros o de un período de tiempo prolongado en el campo.

En caso de que se produzca un choque que requiera el despliegue de las bolsas de aire delanteras, la bolsa de aire del conductor podría proyectar uno o varios fragmentos de la cubierta de la bolsa de aire hacia los ocupantes, lo cual aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0471209 A / 000000000000135 / 135



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

