



**IMPORTANT SAFETY RECALL INTERIM NOTICE**  
This notice applies to your vehicle, VIN: [REDACTED] 123456  
**Replace Rear Wheel Speed Sensor**  
**NHTSA Recall #21V042**

Mercedes-Benz USA, LLC

Robert Veit  
Managing Director  
Vans USA

March, 2021

21V042  
[REDACTED] 123456

- A safety defect exists in your vehicle.
- Remedy parts are not yet available for your vehicle.
- We will contact you again once parts are available.

Dear Valued Mercedes-Benz Sprinter Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG (“MBAG”), the manufacturer of Sprinter vans, has decided that a defect which relates to motor vehicle safety exists in certain Model Year (“MY”) 2012 - 2018 Mercedes-Benz Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

On certain MY2012- 2018 5-ton Sprinter vehicles that were upfitted into campers or recreational vehicles (“RVs”), one or more of the rear-wheel speed sensors may experience an electrical failure, which potentially could lead to a disablement of the Electronic Stability Control (“ESP”) control unit functions. If ESP control unit functions are disabled, vehicle driving stability may be impacted under certain driving conditions, increasing the risk of a crash.

An authorized Mercedes-Benz Sprinter dealer will replace the rear-wheel speed sensors with new sensors having improved robustness to moisture intrusion.

**Unfortunately, the parts to remedy this issue are currently not yet available.**

We are working to obtain the necessary parts to correct this condition as quickly as possible. As the parts become available, we will send you another letter asking you to take your vehicle to an authorized Mercedes-Benz dealer to have the recall completed free of charge.

Should you have any concerns or questions regarding your vehicle before you receive the next recall letter when parts are available, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-800-367-6372. A vehicle identification number (VIN)-based recall lookup tool on our MBUSA.com website offers a search function that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed.

Please visit [www.mbvans.com/sprinter/owners-resources/recall](http://www.mbvans.com/sprinter/owners-resources/recall) and enter your 17 digit VIN in the VIN Look-up tool.

We also encourage you to sign up for recall alerts at [www.nhtsa.gov/alerts](http://www.nhtsa.gov/alerts).

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

We apologize for any inconvenience this situation may cause you.

Sincerely,

Mercedes-Benz USA, LLC  
A Mercedes-Benz AG Company  
One Mercedes-Benz Drive  
Sandy Springs, GA 30328  
Phone (770) 705-0600

**IMPORTANT**

VIN: [REDACTED] 123456

If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner so that we may contact them.

- EXPORTED
- LEASE, VEHICLE RETURNED
- SCRAPPED
- SOLD
- STOLEN
- OTHER \_\_\_\_\_

NEW OWNER INFORMATION

MY NEW NAME OR ADDRESS IS:

[Grid for Last Name, First Name]

Last Name, First Name

[Grid for Street]

Street

Apt

[Grid for City, State, ZIP]

City

State

ZIP

[Grid for Email Address]

Email Address

[Grid for Phone (numbers only)]

Phone (numbers only)

[Grid for Mobile (numbers only)]

Mobile (numbers only)

\_\_\_\_\_  
Date

\_\_\_\_\_  
Signature