

**2021MY K5, Telluride & Forte Occupant Classification/Detection System Chronology
Basis of Safety Defect Determination 573.6(c)(6)**

February 26, 2021	Supplier informs Kia Motors Mexico (KMM) of calibration issue for certain period of production due to a failed relay in the circuit board of the OCS/ODS unit at plant of circuit board supplier. KMM searched its vehicle production records and determined possible affected vehicle scope (2021 Forte).
March 1-2, 2021	Supplier informs Kia Motors Manufacturing Georgia (KMMG) of the calibration issue for certain period of production. KMMG works with supplier to identify potentially affected parts. KMMG identifies certain K5 and Telluride vehicles equipped with affected component through a review of its vehicle production records.
March 2, 2021	KMM informs Kia Motors North America (KMNA) of issue and confirms based on review of vehicle production records, one (1) Forte vehicle with affected component sold to dealer; remaining Forte vehicles held at plant, at rail or at the port for repair before being sold to dealers.
March 3, 2021	KMMG informs KMNA of calibration issue. KMMG advises majority of vehicles equipped with affected component still at plant; some vehicles in dealer stock or retailed. KMNA works with KMMG to identify affected number of vehicles sold to dealers and/or customers.
March 4, 2021	KMNA decides to recall the 2021MY Kia K5, Telluride and Forte vehicles due to non-compliance with FMVSS 208 concern. KMA advised dealers to hold the potentially affected vehicles in dealer stock until further notice through its Regional Parts & Service Managers. No customer complaints, crash or injuries related to this condition.