

CAMPAIGN LAUNCH STATUS

N607 RECALL - BATTERY GROUND STUD 20-21MY DISCOVERY



SAFETY RECALL N607 BATTERY CABLE GROUND STUD

AFFECTED MODELS	20-21MY Discovery. Extension of the existing N400 recall VIN range to add a further set of vehicles up to new end VIN SALRA2BUXM2453141
VOLUME AFFECTED	1383 USA 83 CAN
REPAIR	The battery cable ground stud may be loose in the body and needs to be replaced. Insufficient ground contact may lead to intermittent operation of electrical equipment and unexpected engine shutdown. A new 6mm ground stud is to be installed above the existing location.
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	July 15 th 2021
Notes	Retailer notification bulletins NAS21.07.001 (CAN and NAS21.07.002(USA) were published July 1 st , 2021 Repair process will be the same as for N400 recall

PRINTED COPIES ARE UNCONTROLLED