



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

March 22, 2022

Ms. Rachel Heineman
Quality & CI Manager
Marion Body Works Inc.
211 W Ramsdell Street
Marion, WI 54950

NEF-107MR
22E-015

Subject: High Pressure Fuel Rail Assembly May Leak Fuel

Dear Ms. Heineman:

This letter serves to acknowledge Marion Body Works Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MARION BODY WORKS/FREIGHTLINER M2/2021
MARION BODY WORKS/INTERNATIONAL SR525/2018
MARION BODY WORKS/KENWORTH T3 SERIES/2020

Mfr's Report Date: March 1, 2022

NHTSA Campaign Number: 22E-015

Components:

FUEL SYSTEM, DIESEL:FUEL INJECTION SYSTEM:FUEL RAIL

Potential Number of Units Affected: 3

Problem Description:

Marion Body Works Inc. (Marion) is recalling certain 2021 Freightliner M2, 2020 Kenworth T3, and 2018 International SR525 emergency vehicles equipped with certain Cummins diesel engines. The sealing washer may not seat correctly in the pilot bore holes, allowing the high-pressure fuel rail assembly to leak.

Consequence:

A fuel leak in the presence of an ignition source increases the risk of a fire.

Remedy:

Cummins service centers will inspect the rail threads and fuel lines, and replace the rail as necessary, free of charge. Owner notification letters were mailed on March 7, 2022. Owners may contact Marion's customer service at 1-715-754-5261. Marion's number for this recall is 20E-032.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Marion Body Works Inc.'s contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement