



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

March 23, 2022

Mr. Fred Imundo
Compliance Coordinator
Navistar, Inc.
2701 Navistar Dr.
Lisle, IL 60532

NEF-107SS
22V-164

Subject: Battery Cable May Become Damaged and Short

Dear Mr. Imundo:

This letter serves to acknowledge Navistar, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

INTERNATIONAL/LT/2018-2023

Mfr's Report Date: March 17, 2022

NHTSA Campaign Number: 22V-164

Components:

ELECTRICAL SYSTEM:12V/24V/48V BATTERY:CABLES

Potential Number of Units Affected: 2,804

Problem Description:

Navistar, Inc. (Navistar) is recalling certain 2018-2023 International LT vehicles equipped with a 1500W Purkeys inverter system. The positive battery cable may be incorrectly routed, causing it to chafe on the side skirt frame and become damaged.

Consequence:

A damaged battery cable can cause an electrical short, increasing the risk of a fire.

Remedy:

Dealers will replace any damaged battery cables and install new inverter cable brackets and saddles, free of charge. Owner notification letters are expected to be mailed May 16, 2022. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 22507.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section. The component does not need to be defective, only what is involved during the repair.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Navistar, Inc.'s contact for this recall will be Sarah Shiver who may be reached by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement