



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

September 14, 2022

Jonathan Gannon
BMW of North America, LLC
150 Chestnut Ridge Road
Woodcliff Lake, NJ 07677

NEF-107DM
22V-672

Subject: Horn Not Attached Securely

Dear Jonathan Gannon:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/CE 04/2022

Mfr's Report Date: September 8, 2022

NHTSA Campaign Number: 22V-672

Components:

ELECTRICAL SYSTEM:HORN

Potential Number of Units Affected: 252

Problem Description:

BMW of North America, LLC (BMW) is recalling certain 2022 CE 04 motorcycles. The horn may be insufficiently attached, allowing it to loosen or partially detach from the motorcycle frame.

Consequence:

A loose or partially detached horn can interfere with motorcycle steering and increase the risk of a crash.

Remedy:

Dealers will remove and reinstall the horn, free of charge. Owner notification letters are expected to be mailed October 31, 2022. Owners may contact BMW customer service at 1-800-525-7417.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

We have received BMW's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.



Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

BMW of North America, LLC's contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement