

Recall Quarterly Report

22V-394

Manufacturer Name : Daimler Trucks North America, LLC

NHTSA Recall No. / MFR Recall No. : 22V-394 /FL-937

Recall Subject : Improperly Installed Steering Shaft Bolt

Owner Notification Beginning Date : AUG 01, 2022

Owner Notification End Date: AUG 01, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JUL 18, 2023	2023-2	3,573	2,108	0	0
3	APR 24, 2023	2023-1	3,573	1,876	0	0
2	JAN 28, 2023	2022-4	3,573	1,564	0	0
1	OCT 28, 2022	2022-3	3,573	979	0	0

This Document Last Updated : JUL 19, 2023

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.