Recall Quarterly Report

22V-681

Manufacturer Name: Daimler Trucks North America, LLC NHTSA Recall No. / MFR Recall No.: 22V-681 /FL952 Recall Subject: Improperly Installed Steering Shaft Bolt Owner Notification Beginning Date: OCT 11, 2022

Owner Notification End Date: OCT 11, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 20, 2023	2023-3	200	145	0	0
3	JUL 18, 2023	2023-2	200	127	0	0
2	APR 24, 2023	2023-1	200	102	0	0
1	JAN 28, 2023	2022-4	200	65	0	0

This Document Last Updated: OCT 24, 2023

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.