## **Recall Quarterly Report**

22V-787

Manufacturer Name : Ford Motor Company NHTSA Recall No. / MFR Recall No. : 22V-787 /22S66 Recall Subject : Fuel Pump Control Module Bracket Not Secured Owner Notification Beginning Date : DEC 01, 2022 Owner Notification End Date: DEC 01, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	OCT 24, 2023	2023-3	26	25	0	0
3	JUL 24, 2023	2023-2	26	24	0	0
2	APR 18, 2023	2023-1	26	20	0	0
1	JAN 24, 2023	2022-4	26	17	0	0

This Document Last Updated : NOV 02, 2023

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7