

Part 573 Safety Recall Report

22V-048

Manufacturer Name : Keystone RV Company

Submission Date : FEB 02, 2022

NHTSA Recall No. : 22V-048

Manufacturer Recall No. : 22-420



Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000
2642 Hackberry Drive Goshen IN
46527

Company phone : 574-535-2100

Population :

Number of potentially involved : 92

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2022 Keystone Raptor

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All Models with Sailun 235/80R16 tires with DOT codes 2020 through 4120
Raptor models count 92

Production Dates : SEP 22, 2020 - DEC 13, 2021

VIN Range 1 : Begin : 4YDF41330MR800483 End : 4YDF42334MR800752

☒ Not sequential

VIN Range 2 : Begin : 4YDFRPT25NR800296 End : 4YDFRPT27NR800493

☒ Not sequential

Vehicle 2 : 2021-2021 Keystone Montana

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All Models with Sailun 235/80R16 tires with DOT codes 2020 through 4120
Montana model count 37

Production Dates : SEP 24, 2020 - OCT 21, 2020

VIN Range 1 : Begin : 4YDF39326M4701494 End : 4YDF32326M4701826

☒ Not sequential

Description of Defect :

Description of the Defect : Sailun Tire of America decided that a defect which relates to motor vehicle safety exists in certain Sailun Specialty Trailer (ST) branded tires. In particular, the ST235/80R16 and the ST235/85R16 manufactured at Sailun's Vietnam plant (1YJ) from the 20th week of 2020 through the 41st week of 2020 are being voluntarily recalled.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The defect is associated with a steel belt package design change that could contribute to a tread belt separation or tread delamination, increasing the risk of a crash.

Description of the Cause : The steel belt package design.

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : Sailun Tire

Component Description : ST235/80R16G

Component Part Number : 527328

Supplier Identification :

Component Manufacturer

Name : Sailun Tire Americas, Inc.,

Address : 211 Hunter's Valley Rd
Woodbridge Foreign States L4H3V9

Country : Canada

Chronology :

1/14/2022 – Tire Supplier of the recall issued by Sailun Tire Americas notified Keystone of an issue that exists with certain Sailun brand tires, Sailun Tire NHTSA Recall Number 21T-018. Investigation opened to research internal tire Identification Number (TIN) records.

1/26/2022 – Investigation of TIN records concluded. Scope and Range complete for pass through recall.

Description of Remedy :

Description of Remedy Program : The remedy is to inspect the tires DOT code and contact Sailun Tire Americas if the DOT codes fall under the recall range. Manufacturer Reimbursement Plan on file as of 10/07/2020. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.

How Remedy Component Differs from Recalled Component : ST235/80R16G Sailun Tires within the listed DOT 1YJ and the last four digits of the DOT code 2020 to 4120 are in the affected range. If the factory code is MW, the tire(s) are not affected and no further action is required.

Identify How/When Recall Condition was Corrected in Production : All vehicles with affected tires were shipped prior to notification being received by Keystone RV.

Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : MAR 22, 2022 - MAR 22, 2022

Planned Owner Notification Date : MAR 22, 2022 - MAR 22, 2022

* NR - Not Reported