OMB Control No.: 2127-0004

## Part 573 Safety Recall Report

### 22V-157

**Manufacturer Name:** Winnebago Towable

**Submission Date:** MAR 15, 2022 **NHTSA Recall No.:** 22V-157

**Manufacturer Recall No.:** NR



#### **Manufacturer Information:**

Manufacturer Name: Winnebago Towable

Address: 201 14th Street

Middlebury IN 46540

Company phone: 825-5250

### **Population:**

Number of potentially involved : NR Estimated percentage with defect : 1 %

### **Vehicle Information:**

Vehicle 1: 2022-2022 Winnebago TBD

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Based on Norco delivery dates of affected frames in recall 22E-003

Production Dates: SEP 09, 2021 - OCT 31, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

### **Description of Defect:**

Description of the Defect: On the frames used to build these RVs, some couplers where not fully welded /

welds were missing

Reference recall E22-003

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The coupler welds could fail and may cause trailer/tow vehicle separation

resulting in a crash which could result in serious injury or death.

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

### **Involved Components:**

# Part 573 Safety Recall Report

22V-157

Page 2

Component Name 1: Coupler

Component Description: NR

Component Part Number: CA-5400-O and CA-5400-B

### **Supplier Identification:**

### **Component Manufacturer**

Name: Pacific Trailer Products, Inc

Address: 19215 SE 34th Street

Camas Washington 98607

**Country: United States** 

### **Chronology:**

March 8, 2022 Norco (frame mfg) sent notice of recall E22-003 March 8 2022 to present Recall group has meetings and researching affected product March 15, 2022 - 573 notice submitted to portal

### **Description of Remedy:**

Description of Remedy Program: Winnebago service centers will inspect and if needed replace coupler

How Remedy Component Differs The recall coupler will have spot welds, remedy component will have full

from Recalled Component: beads of weld

Identify How/When Recall Condition couplers were inspected for full weld

was Corrected in Production:

### **Recall Schedule:**

Description of Recall Schedule : TBD

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

<sup>\*</sup> NR - Not Reported