OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-289

Manufacturer Name: KZRV, L.P.

Submission Date: JUN 10, 2022

NHTSA Recall No.: 22V-289

Manufacturer Recall No.: KZ-2022-02



Manufacturer Information:

Manufacturer Name: KZRV, L.P.

Address: 0985 N 900W

Shipshewana IN 46565

Company phone: 800-768-4016x154/153

Population:

Number of potentially involved: 11,906 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2021-2022 KZ RV Escape

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Notice from vendor of defective Quick Connect Brass Quick Connect fitting.

Production Dates: JUL 01, 2021 - APR 26, 2022

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2021-2022 KZ RV SportTrek

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Notice from vendor of defective Quick Connect Brass Quick Connect fitting.

Production Dates: JUL 01, 2021 - APR 26, 2022

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 3: 2021-2022 KZ RV Sonic

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Notice from vendor of defective Quick Connect Brass Quick Connect fitting.

Production Dates: JUL 01, 2021 - APR 26, 2022

Vehicle 4 : Vehicle Type : Body Style : Power Train :		eV Stratus					
Descriptive Information :	Notice from vendor of defective Quick Connect Brass Quick Connect fitting.						
Production Dates:	JUL 01, 2021 - APR 26, 2022						
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
Vehicle Type : Body Style : Power Train :	NR			r Connect Brass Quick Conn	nect fitting.		
Production Dates:	JUL 01, 2021 - APR 26, 2022						
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential		
Vehicle Type : Body Style : Power Train :	NR Notice from ven JUL 01, 2021 - A	dor of defective	· Quick End :	Connect Brass Quick Conn	nect fitting. ☐ Not sequential		
Vehicle Type : Body Style : Power Train :	NR Notice from ven	dor of defective		Connect Brass Quick Conn	nect fitting.		
VIN Range 1:		NR	End:	NR	■ Not sequential		
Vehicle 8: 2021-2022 KZ RV Sportsmen Classic Vehicle Type: TRAILERS Body Style: Power Train: NR Descriptive Information: Notice from vendor of defective Quick Connect Brass Quick Connect fitting. Production Dates: JUL 01, 2021 - APR 26, 2022							
VIN Range 1:	Begin:	NR	End:	NK	☐ Not sequential		

Vehicle 9: 20	021-2022 KZ RV	Connect						
Vehicle 9: 20	021-2022 KZ RV	Connect						
Vehicle Type: TR Body Style: Power Train: NF		Connect						
Descriptive Information: No	Notice from vendor of defective Quick Connect Brass Quick Connect fitting.							
•	JUL 01, 2021 - APR 26, 2022							
VIN Range 1:Beg		•	End:	NR	☐ Not sequential			
	5							
Vehicle 10: 20 Vehicle Type: TR Body Style: Power Train: NF	RAILERS	⁷ Durango						
Descriptive Information: No	Notice from vendor of defective Quick Connect Brass Quick Connect fitting.							
Production Dates: JU	JUL 01, 2021 - APR 26, 2022							
VIN Range 1:Beg	gin:	NR	End:	NR	■ Not sequential			
Vehicle 11: 20 Vehicle Type: TR Body Style: Power Train: NR Descriptive Information: No Production Dates: JU VIN Range 1: Beg Vehicle 12: 20 Vehicle Type: TR	RAILERS R otice from vend UL 01, 2021 - AP: gin: 021-2022 KZ RV	or of defective R 26, 2022 NR		·	ect fitting.			
Body Style :								
Power Train: NF								
Descriptive Information : Notice from vendor of defective Quick Connect Brass Quick Connect fitting.								
Production Dates: JU					_			
VIN Range 1:Beg	gin:	NR	End:	NR	■ Not sequential			
Vehicle 13: 20 Vehicle Type: TR Body Style: Power Train: NR Descriptive Information: No	RAILERS R otice from vend	or of defective	Quick (Connect Brass Quick Conn	ect fitting.			
Production Dates: JUI VIN Range 1: Beg		k 26, 2022 NR	End:	NR	■ Not sequential			
viiv ivange 1 . Deg	5	1110	LIIU .	IVIV	Not sequential			

Description of Defect:

Description of the Defect: These vehicles may be equipped with quick connect couplers supplied to KZ by

Enerco Group, Inc. Enerco has issued a recall for these fittings.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The defective fittings may crack and leak, causing a risk of fire.

Description of the Cause: According to the manufacture, some of the brass components may have

porosity, contamination, and carbon.

Identification of Any Warning The crack in the fitting may be visible.

that can Occur:

Involved Components:

Component Name 1: Propane quick connect

Component Description: NR Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Enerco Group, Inc. Address: 4650 W. 160th Street

Cleveland Ohio 44135

Country: United States

Chronology:

4/20/2022 - KZ is notified by Enerco of their recall. Investigation ensues regarding KZ's usage.

4/21/2022 - Enerco provides information regarding supplied product.

4/23/2022 - KZ confirms use of the fittings and continues investigation to determine affected units.

4/25/2022 - KZ holds a safety committee meeting and votes to issue a recall.

4/26/2022-5/19/2022- KZ continues to review purchase orders and production data. Determines that a number of included VINs were not equipped with the defective fitting and reduces the total population. No warranty data, customer complaints or other data has been received.

Description of Remedy:

Description of Remedy Program : Replace the fittings. How Remedy Component Differs Proper quality brass.

from Recalled Component:

Identify How/When Recall Condition Supplier corrected.

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: KZ will notify the dealers and owners of these recreational vehicles by

letter. Reimbursement will follow the general reimbursement plan on file with NHTSA. A final copy of the owner letter and dealer repair

instructions will be provided to NHTSA.

Planned Dealer Notification Date : JUN 30, 2022 - JUN 30, 2022 Planned Owner Notification Date : JUN 30, 2022 - JUN 30, 2022

^{*} NR - Not Reported