

Part 573 Safety Recall Report

22V-385

Manufacturer Name : Roadtrek Inc.

Submission Date : JUN 15, 2022

NHTSA Recall No. : 22V-385

Manufacturer Recall No. : NHTSA Recall 22E021



Manufacturer Information :

Manufacturer Name : Roadtrek Inc.

Address : 20 Tyler Street
Cambridge 00 N1T0E4

Company phone : 519-745-1160

Population :

Number of potentially involved : 99

Estimated percentage with defect : 100 %

Vehicle Alterer Information :

Vehicle 1 : 2021-2022 Roadtrek Inc All Models

Descriptive Information : Dometic has initiated a recall on their propane cook tops due to a possible leak in the burner control valve.

Production Dates : SEP 17, 2021 - APR 22, 2022

Description of Defect :

Description of the Defect : propane stove burner control valve may have a leak

FMVSS 1 : 301 - Fuel system integrity

FMVSS 2 : NR

Description of the Safety Risk : a propane gas leak could result in an explosion that could cause bodily injury

Description of the Cause : defective component received from supplier

Identification of Any Warning : in the event of a propane leak, the propane gas alarm would be activated that can Occur :

Involved Components :

Component Name : propane cook top

Component Description : burner control valve

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : Dometic Corporation
Address : 5155 Verdant Dr.,
Elkhart Indiana 46516
Country : United States

Chronology :

on May 24 we received a mailed notice from Dometic of a recall on a specific list of cooktop serial numbers for some of the cooktops that they had supplied to us - We immediately searched our inventory to find what defective components we had in stock to sequestered them and then searched our QAR reports to identify vehicles that we had shipped with defective components in them

Description of Remedy :

Description of Remedy Program :	Dometic is supplying replacement cooktops directly to our dealers so that they can replace the defective product on all effected vehicles in the field at no cost to the owner and dealers will be reimbursed for the installation by Dometic
How Remedy Component Differs from Recalled Component :	there is no visually detectable difference
Identify How/When Recall Condition was Corrected in Production :	all inventory was searched to identify defective components and the defective components were marked as defective and removed to our NCR area - all components in vehicles in production were inspected for matching serial numbers of defective components and if they were defective they were removed, marked and placed in the NCR area

Recall Schedule :

Description of Recall Schedule :	All dealers and owners with suspected defective cooktops will be required to inspect the vehicles they have and confirm the cooktop serial number - those cooktops that match the list of defective cooktops will be replaced and the cost of the replacement will be reimbursed by Dometic
Planned Dealer Notification Date :	JUN 20, 2022 - JUN 24, 2022
Planned Owner Notification Date :	JUN 20, 2022 - JUN 24, 2022

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported