

# Part 573 Safety Recall Report

# 22V-389

**Manufacturer Name :** TM Industries**Submission Date :** AUG 30, 2022**NHTSA Recall No. :** 22V-389**Manufacturer Recall No. :** 4T9T**Manufacturer Information :**

Manufacturer Name : TM Industries

Address : 42021 268th Street

Parkston SD 57366

Company phone : 605.951.7580

**Population :**

Number of potentially involved : 10

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2021-2022 TrailManor 2518 series

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : NR

**Descriptive Information :** How recall units were determined. Data Card with model numbers. How they differ?  
Different model numbers.

We received 10 of these models from Dometic Corporation Model number CE99-ZF.

Production Dates : DEC 29, 2021 - APR 13, 2022

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** The 2 burner cook tops installed in these units may have incurred abrasions internally on the metal sealing surface of the burner control valve

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** Increased risk of fire and injury. There is a potential for the gas leak behind the control nob to ignite and create a small flame and present the possibility of a burn to the user.

Description of the Cause : NR

Identification of Any Warning NR  
that can Occur :

**Involved Components :**

Component Name 1 : Dometic model number CE99-ZF-US

Component Description : 2 burner cooktop

Component Part Number : 9600037307

## Supplier Identification :

### Component Manufacturer

Name : Dometic Corporation

Address : 2320 Industrial Parkway  
Elkhart Indiana 46516

Country : United States

## Chronology :

We were notified by Dometic on May 9,2022 about the NHTSA recall of the affected two burner cooktop .We were also notified by NHTSA about this recall. After receiving the notification from Dometic and NHTSA TrailManor issued there own recall regarding the affected cooktop on 5.31.2022

## Description of Remedy :

Description of Remedy Program : Schedule a appointment with a certified Dometic RV dealer. They will contact Dometic and will do the repair and replacement at no cost to the end user.  
If you had to replace the recalled cooktop prior to us issuing a recall and you incurred any expenses regarding this issue please contact TrailManor at paul@trailmanor.com. We will insure that you get reimbursed for all your expenses. Please provide receipts

How Remedy Component Differs from Recalled Component : We only had 10 of the above identified cook tops.

Identify How/When Recall Condition was Corrected in Production : We are no longer using that particular model cooktop.

## Recall Schedule :

Description of Recall Schedule : Dealer letter sent out on May 16, 2022. emails also sent to all dealers.

Planned Dealer Notification Date : MAY 30, 2022 - JUN 30, 2022

Planned Owner Notification Date : MAY 30, 2022 - JUN 30, 2022

\* NR - Not Reported