

Part 573 Safety Recall Report

22V-545

Manufacturer Name : Winnebago Towable

Submission Date : JUL 28, 2022

NHTSA Recall No. : 22V-545

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Winnebago Towable

Address : 201 14th Street

Middlebury IN 46540

Company phone : 825-5250

Population :

Number of potentially involved : 411

Estimated percentage with defect : 22 %

Vehicle Information :

Vehicle 1 : 2022-2022 Winnebago Voyage

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Lippert provided a list then Winnebago used PO and Production production records to capture VINs in that date range.

Production Dates : MAR 28, 2022 - JUN 22, 2022

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : In extreme cases the fabric of the awning could detach from the coach rail and remain attached to the awning frame. This could allow the awning to drop and extend beyond normal operation

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A detached awning could hit someone causing injury or if the frame were to detach when the vehicle is in motion, this could increase the risk of an accident. Winnebago is not aware of any warranty claims, field or service reports, or other incidents related to this issue occurring on Winnebago products.

Description of the Cause : Insufficient weld penetration in some areas between the fabric and the adjoining PVC extruded track.

Identification of Any Warning that can Occur : A visible warning would include seeing a partial weld separation at the ends of the awning roll along the coach/

Involved Components :

Component Name 1 : Awning

Component Description : Lippert electric retractable awnings up to 18' in length

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Lippert

Address : PO Box 2888

Elkhart Indiana 46515

Country : United States

Chronology :

Received E-mail from Lippert on July 20, 2022 and an investigation was started to determine scope of impacted trailers. Safety committee met on July 25 to review findings of the investigation a determined a recall was necessary. July 28, 2022, recall was filed.

Description of Remedy :

Description of Remedy Program : Remedy program will include providing instructions for inspection and repair or replacement as needed of awnings which do not pass the inspection or have an occurrence. If repair or replacement is needed Lippert will supply the necessary items to complete the repair or replace the faulty product. Lippert will reimburse all OEM's, dealers, mobile repair companies and/or consumers for all costs associated with inspection, repair and/or replacement of the affected awnings.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : There are no defective awning at the Winnebago location.

Recall Schedule :

Description of Recall Schedule : Letters will be completed and mailed with in 60 days

Planned Dealer Notification Date : SEP 16, 2022 - SEP 16, 2022

Planned Owner Notification Date : SEP 16, 2022 - SEP 16, 2022

* NR - Not Reported