

Part 573 Safety Recall Report

22V-828

Manufacturer Name : Forest River, Inc.**Submission Date :** NOV 04, 2022**NHTSA Recall No. :** 22V-828**Manufacturer Recall No. :** 501-1571**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 2,707

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2023 Forest River Inc. East to West Alta Travel Trailers

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : According to manufacturing records, the amber and red length indicator lamps began being used in production in October of 2021 and continued to November 1, 2022.

2022	ALTA TRAILERALT1900MMK	187
2022	ALTA TRAILERALT2100MBH	170
2022	ALTA TRAILERALT2350KRK	169
2022	ALTA TRAILERALT2600KRB	385
2022	ALTA TRAILERALT2800KBH	413
2022	ALTA TRAILERALT2810KIK	192
2022	ALTA TRAILERALT2850KRL	222
2022	ALTA TRAILERALT2900KBH	150
2022	ALTA TRAILERALT3150KBH	291
2023	ALTA TRAILERALT1900MMK	57
2023	ALTA TRAILERALT2100MBH	19
2023	ALTA TRAILERALT2210MBH	32
2023	ALTA TRAILERALT2350KRK	40
2023	ALTA TRAILERALT2600KRB	94
2023	ALTA TRAILERALT2800KBH	105
2023	ALTA TRAILERALT2810KIK	56
2023	ALTA TRAILERALT2850KRL	24
2023	ALTA TRAILERALT2900KBH	22
2023	ALTA TRAILERALT3150KBH	79
	Grand Total	2707

Production Dates : OCT 15, 2021 - OCT 31, 2022

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Description of Defect :

Description of the Defect : The red and amber side marker lamps fail to meet the reflectivity requirements under Federal Motor Vehicle Safety Standard (FMVSS) 571.108 "Lamps, reflective devices, and associated equipment".

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The side marker lamps may not reflect light and be conspicuous to other motorists, which may lead to a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : Amber Side Marker Lamp

Component Description : Amber Side Marker Lamp

Component Part Number : S18-AA00-1

Component Name 2 : Red Side Marker Lamp

Component Description : Red Side Marker Lamp

Component Part Number : S18-RR00-1

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On October 31, 2022 during a routine Corporate Standards Audit, it was found that the red and amber side marker lamps fail to meet the reflectivity requirements under FMVSS 571.108 "Lamps, reflective devices, and

associated equipment”.

On November 3, 2022, Forest Rivers Office of Corporate Compliance and the Manufacturing plant were able to determine the scope of vehicles involved.

On November 4, 2022, Forest Rivers Corporate Recall Committee voted to recall

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River Dealer, Service Center will need to install reflective stickers to the vehicles next to the amber and read marker lamps. The stickers and detailed remedy instructions will be included with the owner mailing so that if the owner should choose to, they may install the stickers themselves.

What is the Forest River Customer Service Phone Number? (574)
264-6664

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.
Please send the service invoice to the following address:

East to West
Forest River, Inc.
Attn: WARRANTY MANAGER
3000 County Rd 6 West
Elkhart, IN 46514

How Remedy Component Differs from Recalled Component : At this time, there is not a component change. The Reflex Reflectors will be installed next to the marker lamps.
Involved Components - S18-AA00-1 - Amber Side Marker Lamp & S18-RR00-1 - Red Side Marker Lamp
Replacement Components - RE15AB - Amber Reflex Reflector
RE15RB - Red Reflex Reflector

Identify How/When Recall Condition was Corrected in Production : The week of November 1, 2022, the manufacturing plant sourced the reflex reflectors and is installing them to vehicles next to the amber and red marker lamps.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : DEC 09, 2022 - DEC 09, 2022

Planned Owner Notification Date : DEC 09, 2022 - DEC 09, 2022

* NR - Not Reported