

Part 573 Safety Recall Report

22V-857

Manufacturer Name : Shyft Group**Submission Date :** NOV 18, 2022**NHTSA Recall No. :** 22V-857**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Shyft Group

Address : 1541 Reynolds Road
Charlotte MI 48813

Company phone : 517-543-6400

Population :

Number of potentially involved : 206

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2023-2023 Utilimaster Walk-In Vans

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Vehicles subject to this recall are equipped with a jump seat supplied by Seats, Inc. that may not have a safety clip installed. Shyft continues to investigate this matter.

Production Dates : AUG 16, 2022 - NOV 10, 2022

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The jump seat on the passenger side may be missing a safety clip that prevents the pivot rod from sliding. Without this safety clip, the pivot rod could shift causing the seat to fall.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A seat falling could increase the risk of an injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : This could occur without warning.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported