



---

## **New Safety Recall Advanced Communication – Z25**

FCA US LLC (FCA US) has announced an equipment safety recall on certain Mopar Antilock Brake System (ABS) control module part numbers (PN's)below:

**68453770AB, 68453770AC, 68453770AD, 68477878AB, 68477878AC, 68477878AD, 68563815AB, 68526616AB, 68526242AD.**

### **REASON FOR THIS SAFETY RECALL**

Customers may have purchased the above ABS control module PN's that may have software which prevents the Electronic Stability Control (ESC) telltale lamp from properly displaying under certain conditions. Unexpected performance of the ESC system with no warning to the driver can cause a vehicle crash without prior warning.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.126 S5.3 ESC Malfunction requires that "The vehicle must be equipped with a telltale that provides a warning to the driver of the occurrence of one or more malfunctions that affect the generation or transmission of control or response signals in the vehicle's electronic stability control system." Suspect vehicles may not display the ESC malfunction indicator lamp under certain conditions leaving the driver unaware of degraded ESC system that is not limiting engine torque during an ESC event.

### **SERVICE ACTION**

FCA US will conduct a voluntary safety recall on all affected parts to repurchase suspect ABS control modules. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 1st Quarter of 2022.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations  
FCA US LLC