

**Reference Number: GCUS-3-3136**

**REVISION: N222364860-01 – Safety Recall - Driver Front Airbag Inflator May Rupture**

GLOBAL SAFETY FIELD INVESTIGATIONS

DCS6785

URGENT - DISTRIBUTE IMMEDIATELY

Date: February 8, 2024

Subject: REVISION: N222364860-01 – Safety Recall

Driver Front Airbag Inflator May Rupture

Revised Service Procedure

Models: 2011 – 2012 Chevrolet Silverado 1500, Suburban, and Tahoe

2011 – 2012 GMC Sierra 1500, Yukon, and Yukon XL

To: All General Motors Dealers

This bulletin is being revised to add an additional serial number to the service procedure. Please discard all previous copies of N222364860.

**Question and Answer Document (Q&A)**

Attached to this message you will find a document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS