

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: BMW Delivery Stop: Air Bag Control Unit
Date: Thursday, April 7, 2022 2:46:35 PM

Publish Date: April 7, 2022
From: Technical Service
Expiration Date: April 21, 2022

DCSnet Message
Urgent



Subject: **BMW Delivery Stop: Air Bag Control Unit**

BMW AG is conducting a Voluntary Safety Recall (effective April 7, 2022) on Model Year 2022 - 2023 BMW iX SAV vehicles that were produced between October 14, 2021 and April 7, 2022.

During supplier production, air bag control unit software may not have been programmed to specifications. As a result, the air bag warning lamp in the instrument cluster may not be illuminated when necessary. Note, air bag deployment in a crash is not affected.

Repair is available - Please perform the recall regardless of remedy status. The status will be set to "remedy available" in a few days.

The Recall Notice and Q&A have been attached for further information.

The bulletin will be updated when additional information becomes available.

Sincerely,
Technical Service

Attachments:

[B650322 Recall Notice\[1649356813753\].pdf](#)
 [B650322\[1649356813753\].pdf](#)
 [B650322_22V-xyz-FAQ-\(07Apr2022\)\[1649356813753\].pdf](#) [B650322 Recall Notice\[1649356813753\].pdf](#)
[B650322\[1649356813753\].pdf](#)
[B650322_22V-xyz-FAQ-\(07Apr2022\)\[1649356813753\].pdf](#)

Recipients: BMW Passenger Cars, All Offering, All Region, All Areas, All Departments, All Personnel
BMW SAV (Light Trucks), All Offering, All Region, All Areas, All Departments, All Personnel
BMW i, All Offering, All Region, All Areas, All Departments, All Personnel
BMW Passenger Cars - CC-All