



DATE: June 2022
TO: Micro Bird Distributors
SUBJECT: Recall 22-092-HUC /NHTSA # 22V286
FROM: Marie Claude Gagnon, Product Certification and Specification Specialist, Micro Bird Inc.

This notice is sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Micro Bird has decided that a defect which relates to motor vehicle safety exists in certain MBII and G5 models, year models 2006-2021, built on GM chassis, and manufactured between January 1, 2006, and April 30, 2021.

In certain vehicles, a harness situated near the B-pillar and provided by GM in their chassis, remains unused when the final vehicle is completed. During manufacture, this harness is secured in an opening in the B-pillar. Some edges around and inside the opening may be sharp and the harness may be damaged and become frayed.

If the harness becomes frayed while the cables forming the harness are still connected, a short-circuit may occur, increasing the risk of fire in the vehicle.

To complete this recall, owners will contact you to make an appointment for repair.

We request that you apply for reimbursement via the GOLs claim system with detailed invoices and list of repaired vehicles so we can update our files.

Micro Bird Corporation will provide instructions and parts and reimburse labor to mitigate this recall at no charge.

The allotted time to correct the defect is fifteen (15) minutes per vehicle.

We apologize for any inconvenience this action may have caused and we thank you for your cooperation.