



URGENT SAFETY RECALL BULLETIN

To: Our customers:
Date: 05.16.2022
Manufacturer: TrailManor
Model and year: 2518KB & KS model (2022 model year) (2021 2518KD vin ending in 9166)
NHTSA recall number: 22E-021

Dealers: Upton receipt of the recall notification you are prohibited from selling the affected units until the situation has been remedied

Vin numbers: 4T9T1FE14NP279264, 4T9T1KE14NP279287, 4T9T1FE11NP279271, 4T9T1KE1XNP279326, 4T9T1FE16MP279166, 4T9T1KE18NP279311, 4T9T1KE14NP279340, 4T9T1KE13NP279331, 4T9T1KE10NP279335, 4T9T1KE18NP279342

The above vin numbers are part of the safety recall 22E-021 from NHTSA regarding a potential safety Hazard on a Dometic 2 burner cooktop.

Model number of cook top CE99-ZF,P18022.

Manufacturer: Dometic

Defect: The burner may have incurred abrasions, internally on the mating metal sealing surfaces of the burner control valve which may have led to leaks.

Remedy: Contact Dometic through their recall program and they will furnish you with a new replacement cooktop similar to the one being recalled. You will need to provide Dometic with the model and serial number of the defective part. They will also reimburse the labor for replacement to qualified technicians. Reimbursement to the qualified RV technician will be made once Dometic receives the recall response card documenting the replacement has been made.

Once you have replaced the defective part please contact paul@trailmanor.com.

Regards

Paul Wipf

TrailManor

42021 268th St, Parkston, SD 57366

P: 605-239-4002

E: info@trailmanor.com