



Irbit MotorWorks of America, Inc.

14700 NE 95-th Street, Suite 102, Redmond, WA 98052 Ph: 425.702.8484

Fax: 425.696.0834 jason@ural.com

IMPORTANT SAFETY RECALL

NHTSA Recall No. 22V431

TO: All Ural Dealers

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. Failure to repair within sixty (60) days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the owner may be entitled to an identical or reasonable equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible.

Defect Involved

Irbit Motorworks has determined that a defect which relates to motor vehicle safety exists in certain 2012 to 2017 model Urals. The known assembly defect is specific to aluminum rims used in production between 9/15/2011 and 10/3/2017.

The cause of this defect is improper assembly, specifically over-torque of the wheel spokes that can potentially cause the wheel rim to crack.

Possible consequence of this defect can include broken and/or split rims and possible failure resulting in wheel lock up or damage that could potentially lead to vehicle crash.

All Ural sidecar motorcycles manufactured between 9/15/2011 and 10/3/2017 will be recalled for the replacement of aluminum rims by the servicing dealer using new inventory provided by Irbit Motorworks. This excludes wheel rims previously replaced by warranty and/or under NHTSA Recall No. 13V-507.

Vehicles Involved

This recall includes all 2012-2017 Ural motorcycles with sidecars manufactured between 9/15/2011 and 10/3/2017.

Involved vehicles have been identified by Vehicle Identification Number Computer Listings. Computer listings contain the complete Vehicle Identification Number, owner name and address data, and are furnished to involved dealers with the recall bulletin. Owner name and address data furnished will enable dealers to follow-up with owners involved in this recall.

Sincerely,
Jason Rae

V.P. Operations and Product Support
Jason@ural.com
(425) 702-8484 ext. 105