

Trouble viewing this email? [Open it in your browser >](#)



**Date:** November 17, 2022

**Attn:** All Dealership Personnel

**Subject:** STOP SALE I-22-06 Released

## **IMPORTANT SAFETY NOTICE**

### **Stop Sale**

**IMPORTANT STOP SALE NOTICE!**  
Stop selling affected vehicles immediately.

## **Stop Sale I-22-06**

---

Indian Motorcycle has determined that some Model Year 2022 Chief and Model Year 2021-2022 Scout motorcycles may experience a failure at the fuel pump during operation. If this occurs, the engine may stall increasing the risk of a crash and serious injury.

Indian Motorcycle is currently evaluating a repair procedure for this concern and will provide an update to dealers in the coming weeks.

[View I-22-06 Stop Sale](#)

## **What Dealers Should Do?**

---

As of November 17, 2022, **YOU MUST NOT SELL OR DELIVER** any affected **NEW OR USED 2022 Chief or 2021-22 Scout Models.**

## **Affected Units**

- **2022 Chief**
- **2021-2022 Scout**

Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units.

Please contact Indian Motorcycle Service by phone at 800-330-9407 or through Ask Polaris with any questions or concerns.

---

Thank you for your cooperation in this matter.

Sincerely,

*Indian Motorcycle Service*