## News Channel Update

## Vehicle Compliance & Analysis

| TO: Mercedes-Benz Dealer Principals, General Managers,  | FROM: Gregory Gunther, Department Manager, Vehicle |
|---|--|
| Sales Managers, Service Managers, Parts Managers        | Compliance and Analysis, Engineering Services      |
| RE: Recall Campaign - Initial Notification - STOP DRIVE |  |
| Check and Replace Rear Axle differential                | DATE: December 20, 2022                            |
| MY22 AMG G-Class (463 platform) special edition         |  |
| 4x4 <sup>2</sup>  |  |

## **URGENT RECALL CAMPAIGN INFORMATION**

Please see the attached documents related to the campaign listed above.

**URGENT STOP DRIVE NOTIFICATION** 

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

**Gregory Gunther** 

Department Manager, Vehicle Compliance & Analysis



## Vehicle Compliance & Analysis

| Recall Cam  | paign Initia | al Notification  | December 20, 2022   |
|---|--------------|--|---|
| Campaign No. :  | NHTSA ID     | Campaign Desc. :   | Check and Replace Rear Axle   |
| ТВА   | 22V937       | 22P2197530   | differential  |
| This is to notify you of a new STOP DRIVE <b>Recall Campaign</b> to check and replace the rear axle differential on <b>278</b> Model Year ("MY") 2022 AMG G-Class (463 platform) special edition 4x4 <sup>2</sup> vehicles. The recall campaign will be visible on the www.safercar.gov website and may generate questions from customers. Affected VINs will be flagged in VMI as "PENDING" on <b>December 20, 2022</b> .  |              |  |   |
| Background  |              |  |   |
| Issue   |              | on certain Model Year ("MY") rear axle differential housing differential housing might occonto the roadway. In this case Further, fracturing of the houpower differential on the rea   | , the manufacturer of Mercedes-Benz vehicles, has determined that 2022 AMG G-Class (463 platform) special edition $4x4^2$ vehicles, the might not meet the strength requirements. Cracks in the rear axle rur during vehicle operation, which may lead to differential oil leaking a, a risk of a crash for following vehicle traffic may be increased. Using cannot be ruled out and could lead to an interruption of the raxle, in which a loss of wheel guidance and a loss of propulsion alled out. In this case, the risk of a crash or injury could be increased. |
| What We're Doing  |              | MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will check and, if necessary, replace the rear axle of the affected vehicles. Until the inspection/remedy is completed, affected vehicle owners will be instructed by the MBUSA Customer Assistance Center (CAC) to stop driving their vehicles and will assist to make arrangements with their preferred authorized Mercedes-Benz dealer to have the vehicle towed for inspection. Towing and loaner vehicles, where available, will be offered at no cost to the customer. |   |
| Parts   |              | Remedy is not available at   |   |
| Vehicles Affected   |              |  |   |
| Vehicle Model Year(s)   |              | 2022   |   |
| Vehicle Model   |              | AMG G63 4X4 <sup>2</sup>   |   |
| Vehicle Populations   |              |  |   |
| Total Recall Population   | 1            | 278  |   |
| Total Vehicles in Deale   | r Inventory  | 141  |   |
| Given this notice, it is a violation of Federal law for a dealer to sell or lease any new MY22 AMG G-Class (463 platform) with the special edition 4x42 vehicles in dealer inventory covered by this notification until the vehicle has been repaired. Once the remedy is available, the vehicles will be flagged as "OPEN" and Work Instructions will be available in Xentry. Once the repair is complete, the vehicle may be sold or leased.  Until the inspection/remedy is completed, affected vehicle owners will be instructed by the MBUSA Customer Assistance Center (CAC) to stop driving their vehicles and will assist to make arrangements with their preferred authorized Mercedes-Benz dealer to have the vehicle towed for inspection. |              |  |   |
| Next Steps/Notes  |              |  |   |
| Customer Notification   | Timeline     | starting as early as Decem<br>letters will subsequently be   | Il be instructed by the MBUSA Customer Assistance Center (CAC) ber 19 <sup>th</sup> to stop driving their vehicles. Formal customer notification e sent as soon as they are available. Official owner notifications will pproval of the customer notification letter before February 14,  |
| AOMS/SOMS   |              | AOMs - This recall may ge your dealers ASAP.   | nerate questions from your dealers. Please forward this notice to   |
| 0 ,   | -            | · ·  | maintain a high level of vehicle quality and customer satisfaction.   |

Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.

