



Play-Mor Trailers, Inc.

January 10, 2022

MVR Production

Bhugesh Investments, LLC

1412 Eatonton Road

Madison, GA 30650

RECALL INFORMATION FOR WINNTEC LP REGULATOR MODEL 6020

According to our records, you could have 3 trailers manufactured by Play-Mor with this defective regulator. The trailer serial numbers are listed below:

We have been notified by NHTSA that a safety defect may exist in the above LP regulator, causing it to fail. This could result in excessive output pressure and enlarged flames in gas appliances, increasing the risk of a fire. We purchased this product from UFP Distribution LLC. They were manufactured by Winntec/Deking Corporation in China.

9 Station Hair & Makeup Trailer 1JW100R33K1L18761

9 Station Hair & Makeup Trailer 1JW100R35K1L18762

3 Room Actor Trailer 1JW100R36K1A18750

Please inspect these trailers to determine if they have the WIN 6020 regulator with auto changeover. Remove the regulator and auto changeover and return to it to Play-Mor. It is not necessary to return the hoses, only the regulator and changeover. Play-Mor will send to you replacement regulators with hoses at no charge as soon as they become available. Included with your replacement regulators there will be a prepaid shipping label to return the defective regulators. We apologize for this inconvenience, our customers safety is our top priority. Thank you for your prompt attention to this matter.

Sandy Willibrand

Play-Mor Trailers, Inc.