



PETERBILT MOTORS COMPANY
 A **PERCIP** COMPANY
 1700 WOODBROOK STREET
 DENTON, TEXAS 76205-7864
 940-591-4000

IMPORTANT SAFETY RECALL INFORMATION



U.S. Department of
 Transportation

Issued in Accordance
 With Federal Law



FIRST-CLASS MAIL
 U.S. POSTAGE
PAID
 CLEVELAND, OH
 Permit No. 469



*****SNGL P



T1 P1
 0001



803315-22PBF

SAFETY RECALL NOTICE

Safety Recall Notice: 22PBF

IMPORTANT SAFETY RECALL

March 24, 2023

Subject: Safety Recall: 22PBF - 579 MLU Molded Hood Mirror
NHTSA: 22V940
EXPIRATION DATE: NONE

This notice applies to your vehicle. Your VIN(s) can be found on the bottom or back of this page.

Dear Peterbilt Customer,

Peterbilt has decided that a defect, which relates to motor vehicle safety, exists in certain Model Year 2022-2023 model 579 MLU chassis built between 09/16/2021 and 01/31/2022 that are equipped with optional, molded hood mirrors built without a wire harness or tether. These hood mirrors may experience a pivot joint failure resulting in foreign object debris on the roadway, increasing the risk of a crash and/or injury. These failures can occur with no prior warning.

What is the problem?	MY22-23 model 579 MLU Molded Hood Mirror assemblies built without a wire harness or tether may experience a mirror pivot joint failure.
What will your dealer do?	Inspect optional, molded, hood mirrors for presence of wire harness or tether. If no harness or tether is present, mirrors will be replaced with improved versions that are built with a wire harness or tether.
What should you do?	Please contact your closest dealer to schedule this repair.

Peterbilt Motors Company has initiated this recall to remedy the issue at no charge to you. Your dealer will inspect the optional, molded hood mirrors for the presence of a wire harness or tether. If no harness or tether is present, mirrors will be replaced with improved versions that are built with a wire harness or tether. To find your Peterbilt dealer, please visit the Dealer Locator at www.Peterbilt.com or scan the QR code. When contacting your Peterbilt dealer, reference the Safety Recall number and the NHTSA number. This repair may take up to 1 hour of labor depending on dealer scheduling.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall, or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St, Denton, TX 76205, Attn: Customer Service Department.

If you conclude that Peterbilt has not enabled you to remedy this defect in a reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner. Please send all known ownership and address changes to PBDiv.Warranty.Docs@paccar.com.

We apologize for any inconvenience this preventive procedure may cause and thank you for your participation in helping Peterbilt provide the highest levels of customer satisfaction and service expertise. We value your business and appreciate your ongoing loyalty to Peterbilt and its dealer network. Industry-leading quality, performance and reliability are hallmarks of Peterbilt products, and we thank you for making Peterbilt your truck of choice.

Sincerely,



Michelle Ponsonby
Director of Customer Experience
Peterbilt Motors Company

Scan this QR code to open the
Peterbilt Dealer Locator.



Our records indicate that these vehicles are affected by 22PBF and are owned by [REDACTED]

