



September, 2024

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **22S19 - PHEV Charging Port Resistor/Thermistor Bus Bar**

What is the issue? On your vehicle, it may be possible the bus bar is not fully seated in the charging port harness. The bus bar is part of the system that detects the presence of a connected charge cord.

If the charge port bus bar becomes unseated while driving, a wrench light will illuminate, and when the vehicle speed drops to 2.0 MPH, the vehicle will display a "Stop Safely Now" message on the instrument panel and the vehicle will lose motive power, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support. Thank you for your attention to this very important matter.

Septiembre de, 2024

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2022 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22S19 - Barra de bus de resistor/termistor del puerto de carga de PHEV**

¿Cuál es el problema? Es posible que la barra de bus de su vehículo no se encuentre correctamente asentada en el arnés del puerto de carga. La barra de bus es parte del sistema que detecta la presencia de un cable de carga conectado.

Si la barra de bus del puerto de carga se desplaza mientras maneja, se encenderá una luz de llave y, cuando la velocidad del vehículo se reduzca a 2.0 MPH, aparecerá un mensaje "Deténgase con cuidado ahora" en el panel de instrumentos y el vehículo perderá potencia motriz, lo cual aumenta el riesgo de un choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support. Gracias por su atenciic en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0237953 A / 000000000000226 / 226



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

