



August, 2025

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2020 Escape has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **22S21 - 1.5L Engine Oil Separator**  
**and Description:**

**What is the issue?**            On your vehicle, it may be possible your engine's right hand oil separator was damaged prior to being installed.

A damaged right hand oil separator may leak oil. If an oil leak occurs, you may smell or see oil smoke emanating from the under-hood area or observe oil leaks on or under the engine. In some cases, if sufficient oil accumulates and migrates to an ignition source, an under-hood fire may occur increasing the risk of injury.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

Augusto de, 2025

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2020 Escape las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**            **22S21 - Separador de aceite de motor 1.5L**

**¿Cuál es el problema?**            Es posible que el separador de aceite del lado derecho del motor de su vehículo se haya dañado antes de ser instalado.

Un separador de aceite dañado podría generar una fuga de aceite. Si esto ocurre, podría percibir olor o ver humo de aceite emanando del área debajo del cofre o bien observar fugas de aceite en o debajo del motor. En algunos casos, si se acumula suficiente aceite y este migra a una fuente de encendido, podría producirse un incendio debajo del cofre, lo cual aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C


0008198 A / 000000000000186 / 186



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶



▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶