



December, 2024

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2021 Bronco has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number**    **22S44 - Bronco 5-Door Child Lock Not Functioning**  
**and Description:**

**What is the issue?**

In some of the affected vehicles, a rear door may be opened from the inside of the vehicle when the child safety lock is in the "ON" position. The proper function of the child safety lock prevents the opening of the rear door from inside the vehicle with the child safety lock "ON."

If the child safety lock is not functioning correctly, a rear door may be opened from the inside of the vehicle, despite the indication of the child safety lock in the "ON" position, increasing the risk of injury to an unrestrained second-row occupant.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

December de, 2024

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2021 Bronco las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:**            **22S44 - Seguro para niños de Bronco de 5 puertas no funciona**

**¿Cuál es el problema?**

En algunos vehículos afectados, una puerta trasera se podría abrir desde el interior del vehículo cuando el bloqueo de seguridad para niños está en la posición "activado". La correcta función del bloqueo de seguridad para niños impide abrir la puerta trasera desde el interior del vehículo con el bloqueo de seguridad para niños "activado".

Si el bloqueo de seguridad para niños no está funcionando correctamente, una puerta trasera se podría abrir desde el interior del vehículo, pese a que la indicación de bloqueo de seguridad para niños está en la posición "activado", lo cual aumenta el riesgo de que un ocupante de la segunda fila no sujeto sufra lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).

Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0000036 A / 000000000000718 / 718



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

