



AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd., P.O. Box 2215
Torrance, CA 90509-9870

August 2023

RE: 2006-14 Ridgeline
NHTSA Recall 22V-430

URGENT SAFETY RECALL NOTICE

- **Your vehicle is included in an urgent safety recall and you should have the recall service done immediately.**
- **Any authorized Honda dealer will perform the recall service for FREE.**
- **If you have any questions about this notice, or need assistance with locating a Honda dealership, please visit us at mygarage.honda.com. There you can access our 24/7 virtual agent *Ask Dave*, Live Chat with an agent, use our online dealership locator or send us an email. If you'd like to speak directly to an agent, you can call American Honda's Customer Support & Campaign Center at 1-888-234-2138.**
- **You may also visit www.recalls.honda.com to use *Ask Dave*. Our 24/7 virtual agent.**

Dear FIRSTNAME LASTNAME,

What is the reason for this notice?

Our records indicate that a Safety Recall has not been completed on your 2018 XXXXX (Vehicle Identification Number XXXXXXXXXXXXXXXXXXXX). Corrosion can form on the rear frame due to the accumulation of road de-icing agents mixed with mud and dirt. The fuel tank, which is mounted to the rear frame, can become unsecured as the rear frame deteriorates from corrosion. An unsecured fuel tank may result in a fuel leak and an increased risk of fire in the presence of an ignition source. Loud noises from the rear of the vehicle can alert you in the event the fuel tank becomes unsecured.

What will Honda do?

Your Honda dealer will inspect the rear frame for corrosion. Depending on the extent of the corrosion, the dealer may repair your vehicle by removing the corrosion, applying anti-corrosive wax, and structurally reinforcing the rear frame, where necessary, for **FREE**. Honda estimates that the inspection and possible repair will range from approximately 30 minutes to 3 hours and 15 minutes to complete. However, your dealer can provide you with a better estimate of the overall time for this service visit, as it may be necessary to make your vehicle available for a longer period of time. If the rear frame cannot be repaired, Honda may offer to repurchase the vehicle from you.

We apologize for any inconvenience this recall may cause you.

Sincerely,

American Honda Motor Co., Inc.

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SERVICE BULLETIN #22-021 / DEFECT #6LC00/ SYMPTOM #LCD00



AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd., P.O. Box 2215
Torrance, CA 90509-9870

Agosto del 2023

RE: Ridgeline 2006-14
Campaña de seguridad NHTSA 22V-430

NOTIFICACIÓN URGENTE DE CAMPAÑA DE SEGURIDAD

- **Su vehículo está incluido en una campaña de seguridad urgente y usted debe completar inmediatamente el servicio de la campaña.**
- **Cualquier concesionario autorizado Honda podrá realizar de forma GRATUITA el servicio de la campaña.**
- **Si tiene alguna pregunta acerca de esta notificación o si necesita ayuda para ubicar a un concesionario Honda, puede visitar mygarage.honda.com. Si les gustaría hablar directamente con un agente, por favor comuníquese con el Centro de Apoyo al Cliente y Campañas de American Honda al 1-888-234-2138.**
- **Usted también puede visitar www.recalls.honda.com para usar.**

Estimado FIRSTNAME LASTNAME,

¿Cuál es el motivo de esta notificación?

Nuestros registros indican que no se ha completado una Campaña de Seguridad en su XXXXX 2018 (Número de identificación del vehículo XXXXXXXXXXXXXXXXXXXX). La corrosión se puede formar en el bastidor trasero debido a la acumulación de agentes descongelantes para las carreteras mezclados con lodo y mugre. El tanque de combustible, el cual está montado al bastidor trasero, podría no estar asegurado en la medida que el bastidor trasero se deteriora debido a la corrosión. Un tanque de combustible no asegurado puede ocasionar una fuga de combustible y aumentar el riesgo de fuego en la presencia de una fuente de ignición. Ruidos intensos provenientes de la parte trasera del vehículo le pueden alertar en el caso de que el tanque de combustible no este asegurado.

¿Qué hará Honda?

Su concesionario Honda inspeccionará el bastidor trasero en busca de corrosión. Dependiendo de la extensión de la corrosión, el concesionario puede reparar su vehículo de forma **GRATUITA** retirando la corrosión, aplicando cera anticorrosiva y reforzando estructuralmente el bastidor trasero, donde sea necesario. Honda estima que la inspección y la posible reparación tomará aproximadamente entre 30 minutos a 3 horas y 15 minutos para completar. No obstante, su concesionario le puede ofrecer un mejor estimado del tiempo total de esta visita de servicio, ya que pudiera ser necesario que su vehículo esté disponible por un periodo más largo. Si el bastidor trasero no se puede reparar, Honda podría ofrecerle comprarle el vehículo.

Le pedimos disculpas por cualquier inconveniente que esta campaña de seguridad pudiera causarle.

Atentamente,

American Honda Motor Co., Inc.

AVISO: Si este es un vehículo arrendado, por favor envíe esta notificación al arrendatario.

PARA USO DEL CONCESIONARIO SOLAMENTE: REFERENCIA BOLETÍN DE SERVICIO #22-021 / DEFECTO #6LC00 / SÍNTOMA #LCD00