



L I N C O L N

Lincoln
P.O. Box 1904
Dearborn, Michigan 48121-1904



0003250 01 / 000001026 / 11



February 2024



***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 Navigator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

KEY INFORMATION

- Your vehicle is involved in an important safety recall
- Your safety is important to us. Schedule an appointment to have service procedure completed
- This procedure will be performed free of charge

Recall Number 22C14 - Headlamp Control Module Inop and Description:

What is the Issue? It may be possible for your vehicle to experience a loss of side marker lamps, daytime running lamps (if equipped), and/or other lighting features, due to a software error in the headlamp control module (HCM). If your vehicle experiences this concern, there will be a pop-up message in the cluster stating, "Advanced front lighting features temporarily unavailable".

This may result in a loss of function to side marker lamps and, daytime running lamps (if equipped), increasing the risk of a crash.

What Are We Asking You To Do? Please contact your dealer to schedule an appointment to have this important service procedure completed. If you do not already have a servicing dealer, you can access lincoln.com/support for dealer addresses, maps and driving instructions.

The vehicle owner is responsible for having this service action performed. Lincoln reserves the right to deny coverage for any vehicle damage that may result from failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

Service Assistance: If you have additional questions, please contact the Lincoln Customer Relationship Center at 1-866-436-7332 and one of our representatives will be happy to assist you. For the hearing impaired call 1-800-232-5952 (TDD). Office Hours are Monday through Friday: 8:00AM - 5:00PM (Your Local Time).

If you wish to contact us through the Internet, our address is: lincoln.com/support.

If your authorized dealer has recently completed this recall repair, please disregard this reminder.

We apologize for any inconvenience this may cause and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

Thank you for your attention to this important matter.

Lincoln



L I N C O L N

Lincoln
P. O. Box 1904
Dearborn, Michigan 48121



0003250 01 / 000001026 / 11



Febrero de 2024



***** RECORDATORIO DE CAMPAÑA DE SEGURIDAD IMPORTANTE *****

Según nuestros registros, en su 2022 Navigator no se han realizado las reparaciones necesarias correspondientes a esta campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

INFORMACIÓN CLAVE

- Su vehículo ha sido incluido en una importante campaña de seguridad.
- Su seguridad es muy importante para nosotros. Programe una cita para completar el procedimiento de servicio.
- Este procedimiento se llevará a cabo sin costo alguno.
- *Si necesita ayuda o tiene alguna pregunta, por favor llame al Centro de Relación con Clientes al 1-866-436-7332 y presione 2 para Español.*

Número y descripción de la campaña:

22C14 - Módulo de control de los faros no funciona

¿Cuál es el problema?

Es posible que su vehículo experimente una pérdida de las luces de posición laterales, luces de circulación diurna (si están equipadas) u otras funciones de las luces, debido a un error de software en el módulo de control de los faros (HCM). Si su vehículo experimenta este problema, en el tablero aparecerá un mensaje que señala "Función de luces delanteras avanzadas temporalmente no disponible".

Esto podría generar una pérdida de la función de las luces de posición laterales y de las luces de circulación diurna (si están equipadas), lo cual aumenta el riesgo de choque.

¿Qué le solicitamos hacer?

Comuníquese con su distribuidor a fin de programar una cita para llevar a cabo este importante procedimiento de servicio. Si aún no tiene un distribuidor para realizar el servicio, puede acceder a lincoln.com/support para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.

El propietario del vehículo es responsable de realizar estas acciones de servicio. Lincoln se reserva el derecho de negar la cobertura en caso de que el vehículo hubiese sufrido daños por no haber realizado la campaña de manera oportuna. Por lo tanto, le solicitamos que realice esta campaña lo antes posible.

Servicio de asistencia:

Si tiene preguntas, comuníquese con el Centro de Relación con Clientes de Lincoln al 1-866-436-7332 y uno de nuestros representantes con gusto lo atenderá. Las personas con problemas de audición pueden llamar al 1-800-232-5952 (TDD). El horario de atención es de lunes a viernes, de 8:00 a.m. a 5:00 p.m. (hora local).

Si desea comunicarse con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Si ya realizó esta reparación en su distribuidor autorizado, ignore este aviso.

Lamentamos cualquier inconveniente causado y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

Gracias por su atención en este asunto sumamente importante.

Lincoln