



February, 2025

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2021 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **22S53 - F-150 Loss of Mobility**
and Description:

What is the issue? On your vehicle, underbody insulator(s) may have been installed in error. When present, underbody insulators may loosen and contact the aluminum driveshaft, resulting in marking or scoring of the driveshaft. Continued contact may result in driveshaft fracture.

A fractured driveshaft poses the risks of loss of motive power while driving, unintended vehicle movement while the vehicle is in park if the parking brake is not applied, and secondary damage to surrounding components. A fractured driveshaft may also contact the ground which may cause loss of control of the vehicle while driving. A fractured driveshaft increases the risk of injury or crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2025

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

SegUR nuestros registros, no se realizaron en sur 2021 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22S53 - F-150 Pérdida de movilidad**

¿Cuál es el problema? Es posible que en su vehículo, por error, se hayan instalado aisladores en la parte inferior de la carrocería. Cuando están presentes, los aisladores de la parte inferior de la carrocería podrían aflojarse y tener contacto con la flecha de mando de aluminio, lo que genera marcas o rayados de la flecha de mando. El contacto continuo podría tener como resultado la fractura de la flecha de mando.

Una fractura de la flecha de mando pone en riesgo la pérdida de la potencia motriz mientras maneja, un movimiento accidental del vehículo mientras está en estacionamiento si el freno de estacionamiento no se aplica y daño secundario en los componentes de los alrededores. Una flecha de mando fracturada también podría entrar en contacto con la tierra que podría causar la pérdida de control del vehículo mientras maneja. Una flecha de mando fracturada aumenta el riesgo de choque o de sufrir lesiones o choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0000035 A / 000000000000394 / 394



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

