



Indian Motorcycle Company
P.O. Box 47700
Medina, MN 55340-9960



SECOND NOTICE!

**ACTION
REQUIRED**

IMPORTANT SAFETY RECALL NOTICE!

VIN

First Name Last Name

Address

City, State ZIP




For the latest update on this safety recall, visit
<https://www.polaris.com/en-us/on-road-recalls/>.

CONTACT YOUR AUTHORIZED POLARIS DEALER TO SCHEDULE AN APPOINTMENT TO HAVE THE REPAIRS PERFORMED!

First Name Last Name,

Our records currently indicate you have not had recall
I-22-06 completed on your affected vehicle.



Indian Motorcycle has determined that some Model Year 2022 Chief and Model Year 2021-2022 Scout motorcycles may experience a failure at the fuel pump during operation. If this occurs, the engine may stall increasing the risk of a crash and serious injury.

*If you need assistance contacting or locating an Indian Motorcycle dealer,
visit <https://www.indianmotorcycle.com/en-us/dealer-locator/>.*

THIS WORK WILL BE PERFORMED BY YOUR DEALER AT NO COST TO YOU!