



March, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2021 Bronco has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 22S77 - Side Crash Sensor
and Description:

What is the issue? On your vehicle, the side impact sensors may not have been properly installed.
A side impact sensor that is not installed correctly may not detect certain side impact events. Incorrect side impact sensor readings could cause the affected air bags to unintentionally deploy or to not deploy when intended, increasing the risk of injury in a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Marzo de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en su 2021 Bronco las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 22S77 - Sensor de choque lateral

¿Cuál es el problema? Los sensores de impacto lateral de su vehículo podrían no estar correctamente instalados.
Un sensor de impacto lateral no instalado correctamente podría no detectar algunos eventos de impacto lateral. Las lecturas incorrectas del sensor de impacto lateral podrían hacer que las bolsas de aire afectadas se desplieguen accidentalmente o que no se desplieguen cuando sí deberían hacerlo, lo cual aumenta el riesgo de sufrir lesiones en caso de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


0658859 A / 000000000000484 / 484



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶



▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶