

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER												
Safety Recall 42L8	Safety Recall	42L8	What vehicles are included in Safety Recall 42L8?	<table border="1"> <thead> <tr> <th>Country</th> <th>Beginning Model Year</th> <th>Ending Model Year</th> <th>Vehicle</th> </tr> </thead> <tbody> <tr> <td>USA</td> <td>2022</td> <td>2022</td> <td>TAOS</td> </tr> <tr> <td>USA</td> <td>2021</td> <td>2022</td> <td>TIGUAN</td> </tr> </tbody> </table>	Country	Beginning Model Year	Ending Model Year	Vehicle	USA	2022	2022	TAOS	USA	2021	2022	TIGUAN
Country	Beginning Model Year	Ending Model Year	Vehicle													
USA	2022	2022	TAOS													
USA	2021	2022	TIGUAN													
			What is the safety concern for Safety Recall 42L8?	Vehicles included in this recall may have been assembled with incorrectly manufactured rear suspension knuckles. In the event of a rear suspension knuckle breakage, the stability in the rear suspension will be compromised. Depending on the traffic/driving circumstances and driver behavior, this situation could pose a risk of a crash.												
			What is the repair for Safety Recall 42L8?	Inspect and, if necessary, replace one or both rear suspension knuckles.												
			When will the repair for Safety Recall 42L8 be available?	Repairs for this recall have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer .												