

Title:

BMW Safety Recall 22V-614: EGR Cooler

Text:

The engine's Exhaust Gas Recirculation (EGR) Cooler could develop an internal leak. Cooling fluid could mix with typical diesel engine soot deposits. With high temperatures normally present in the EGR module, this might result in smoldering particles. If these particles contact the engine intake manifold, they could create small holes due to melting, increasing the risk of a fire.

Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.

Advise all drivers of this important information.

For the latest updates to this recall, please visit bmwusa.com/recall.

Short Text:

Important Safety Recall 22V-614: EGR Cooler. Contact an authorized BMW center immediately to get your vehicle repaired for FREE. For updates to this recall, please visit bmwusa.com/recall. Dealer locator: bmwusa.com/dealer.

Pop-Up:

Important Safety Recall: Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.